



에르도스 (미얀마) 니트유한회사
ERDOS (MYANMAR) KNITWEAR CO., LTD.

목록

CONTENT



공장소개

**BREIF
INTRODUCTION**



품질관리

**QUALITY
MANAGEMENT**



생산과정

**PRODUCTION
WORKFLOW**



제품전시

PRODUCTS



가지속발전

**SUSTAINABLE
DEVELOPMENT**

Brief Introduction

에르도스(미얀마)니트유한회사는 미얀마 양공 공업원구에 위치하여, 양공시 중심과 25KM거리, 양공시 상징인 쉐다곤 파고다와 15 KM의 거리에 위치해 있으며 교통이 편리함.


Erdos (Myanmar) Knitwear Co. ,Ltd. is an overseas cashmere knitting factory in Yangon ,Myanmar, which is affiliated to Inner Mongolia Eerduosi Resources Co., Ltd. It is 25Km to the city center and 15Km to Shwedagon Pagoda, showing the convenient traffic advantages.



Factory layout

총투자 금액 340만 달러 ,면적 10800평 규모로 완공되어,생산능력을 갖추고 있음.

The project has a total investment of 3.4 million US dollars, covering 10800 square meters. And the project was completed at the end of September in 2017, now qualified with factory audit and bulk production.



수직생산 18라인을 도입하여, 편직, 링킹, 세척, 후가공, 검사 설비 440대(세트), 직원 421인.

The 18 sets of full vertical production line have been introduced from knitting, linking, washing, final finishing and inspection etc., with a total of 440 sets of equipment and a total of 421 member workers.

생산능력

Capacity


아이롱 Ironing

30 대 (Sets)  x 3000 / 일 (Day)

2019년 아이롱대 30대 증설

Will add 30 ironing machine in 2019.

완제품검사 Garment inspection

x 24  x 2500 / 일 (Day)

2019년 테스트 등 10대 증설

Will add 10 inspection lights in 2019.

세척 Washing

 x 2500 / 일 (Day)

2019년 세척,건조,탈수기 총 9대 증설

Will purchase another 9 machines in 2019.

품질검사 Quality Check

 x 17  x 2500 / 天 (Day)



편직설비 60대, 12GG Cixing

12GG Cixing knitting machine x 60 set


 x 1000 / 일 (Day)

현재 전체 18 생산 라인 가동 중

18 sets of full vertical production line have been introduced. 6 of them are working.


 x 60 / 라인 (Set)  x 1800 / 일 (Day)

Vacant capacity in 2020



현재 편직 유희생산능력 27.5만매, 완제품유희생산능력 44.8만매. 편직기 100대 2020/21년 증설 예정.

Our available capacity is 275000 pcs for knitting, and 448000 pcs for finishing. We are planning to increase 100 sets of SHIMASEIKI.





표준 라이트 박스.다종한
환경의 라이트를
연출.D65, TL83, TL84,
F/A와 자외선 등.

Standard light box,
including D65, TL83,
TL84, F/A and UV etc.



현지 검사 파넬
20대.편직 불량 검사.

Panel quality check.



세탁 전후 불량검사.

Light inspection




검침기

HASHIMA metal
detection.



건조기.미얀마의 습한
기후로 인한 습기와
곰팡이를 방지.

The moisture in Myanmar
is high, so we need
dehumidification to avoid
mildew.



창고 Warehouse



편직 Knitting



링킹 Linking



세탁 Washing



검사 Quality check



포장 Packing



발송 Shipping

安全技术说明书
ALBAFIX ECO

第一部分 物质/制剂及公司/企业标识

产品名称: ALBAFIX ECO
物质/制剂的使用: 纺织化学品
供应商: 亨斯曼化工(上海)有限公司
地址: 上海南京西路8号万都中心4601-4609室
邮编: 200036
电话: +86 21 2208 7668
传真: +86 21 2208 7688

亨斯曼纺织效果
Room 4604
4608 Media Centre
8 Singyi Rd.
Shanghai 200036
Tel.: +86 21 2208 7660
Fax: +86 21 2208 7688

紧急电话号码(24h/7day): 欧洲: +32 30751234
美洲: +1 703 527 3887
亚洲: +82 30751235
亚太区: +65 6336 6911
中东: +96 20 39373888
印度: +91 22 40 506 333
美国及加拿大: 800 424 9300

本安全技术说明书责任人的e-mail地址: pshs_t@huntsman.com

第二部分 危险标识

物质或混合物的分类: 危害水生环境-慢性危险-2


化学品分类和标签全球协调系统(GHS)标签要素

警示词: 无信号词

危险性说明: 对水生生物有毒并具有长期持续影响。

防范说明: 禁止排入环境, 收集泄漏物, 收集废弃物, 安全储存, 废弃处置


程序号: 1

污水处理流程示意图

锅炉大气污染物排放检测综合报告
报告编号: OXS1807007


使用单位	ERDOS(MYANMAR)KNITWEAR CO,LTD		
使用地址	PLOT NO:486-487,YAW A TWIN WUN U PHOE HLAING ST SHWELIN BAN INDUSTRIAL ZONE,HELAING THAR YAR TOWNSHIP YANGON		
锅炉名称	全自动燃油(气)蒸汽锅炉	锅炉型号	LSS2-1.0-Y/Q
额定出力	2.0 t/h	产品编号	17LSY2011
使用燃料	柴油	除尘方式	-----
脱硫/脱方式	-----	测试日期	2018-7-18
锅炉制造单位	欧雷玛(广州)机械有限公司	检测地点	使用单位锅炉房内
检测标准	China: 锅炉大气污染物排放标准 GB13271-2014		
检测结果及结论: mg/Nm ³			
检测部位	检测项目	标准浓度值	实测浓度值
烟囱	粉尘颗粒	≤30	24
	SO ₂	≤200	138
	NOx	≤250	213
	烟气黑度	≤1	0.74
检测仪器	德国(菲素)AFRISO烟气分析仪 Multilyzer STe (M60)		
测量范围:	CO (一氧化碳), O ₂ (氧), NOx (氮氧化物), SO ₂ (二氧化硫)		
检测仪器	德国(菲素)AFRISO烟气分析仪, 测量范围: 粉尘颗粒		
检测结论:	锅炉燃料使用为柴油, 经仪器检测结果分析, 判定合格。本结果只对检测时的工况结果负责。建议下次检测日期: 2019-7-18		




화학품관리
Chemical management




수원정화시스템
Water purification system



오수처리시스템
Sewage treatment system



환경보호레포트
EIA report



보일러,발전기
Boiler and electric generator

가지속발전

Sustainable development



Producer : ERDOS (MYANMAR) KNITWEAR COMPANY LIMITED
 DBID : 373743 and Audit Id : 111084 Audit Date : 30/10/2017
 Audit Type : Full Audit



Audit Details	
Audit Range :	<input checked="" type="checkbox"/> Full Audit <input type="checkbox"/> Follow-up Audit
Audit Scope :	<input checked="" type="checkbox"/> Main Auditee <input type="checkbox"/> Main Auditee & Farms
Audit Environment :	<input checked="" type="checkbox"/> Industrial <input type="checkbox"/> Agricultural
Audit Announcement :	<input checked="" type="checkbox"/> Fully-Announced <input type="checkbox"/> Fully-Unannounced <input type="checkbox"/> Semi-Announced
Random Unannounced Check (RUC) :	No
Audit extent (if applicable) :	none
Audit Interferences or contingencies (if applicable) :	none
Overall rating :	C
Need of follow-up :	Yes If YES, by : 02/11/2018

Rating per Performance Area (PA)													
PA 1	PA 2	PA 3	PA 4	PA 5	PA 6	PA 7	PA 8	PA 9	PA 10	PA 11	PA 12	PA 13	
D	C	A	A	B	A	B	A	A	A	A	D	A	

Executive summary of audit report

The auditee was located at PLOT NO. 486, 487, MYAY TAING BLOCK NO. 25, SHWE LIN BAN INDUSTRIAL ZONE, HLAING THARYAR TOWNSHIP, YANGON REGION, MYANMAR that address had been shown on the official license, Myanmar Investment Commission Permit (MIC). It occupied one flat production building for all production process and warehouse with total 9,432 S.Q. meters, there was partial 2nd floor as office at the side near the factory gate, one small size building as generator/power distribution room, one 3-storey dormitory building with total 20 rooms for 6 Chinese officers, no dormitory or kitchen provided for workers, only the canteen provided for workers for their own taken meals.

The main products were CASHMERE SWEATER with main production processes: Knitting, Linking, Sewing, Ironing, QC and Packing.

Only the auditee had been located at the boundary without any shared processes or workers; per management interview and production records review, the peak season was not obvious. It was established on 13 Jan. 2017 that shown on business license and started mass production since 1 Jul. 2017. (As the auditee started mass production since 1 Jul. 2017, the total turnover (In Euros) was estimated based on current manpower and production lines capacity.) There were total 248 employees on the audit day including 6 Chinese management officers; all of them were recruited by the auditee directly except 9 security guards subcontracted from Galaxy One Private Limited. During the audit days, 2 linking lines kept blank, as explained by management representative, these lines were prepared for the order in coming months, they would import more linking machines if production order increased. The other production processing process (knitwear washing) had been installed for pilot run, and waste water treatment center was still in the constructing process, not accomplished till the end of the audit duration. Confirmed by management interview, the milling process was prepared for specific client order in future.

The audit man days had been updated from 3 to 3.6 as interpreter man day included. The management team was cooperated with the audit team; no any access denied for any buildings, no any obstruction or limits for photos taken, all interviewees had been sampled by audit team randomly without any influence or external disturbance by the management team, all necessary documents had been provided promptly, e.g. production records and QC daily records.

The audit findings and deadline date of corrective action had been understood and accepted by management representative. Onsite audit findings report had been described in bilingual version including English version for Management team and Burmese version for worker representative, they could understand the content of the report well. As the local language, Burmese fonts, can not be recognized by the online platform, so the online report was only in English version.







감사합니다

THE END